



Quick Start Guide



Committed to Excellence. Dedicated to Quality. Certified to ISO 9001:2008 in Manufacturing Centers Worldwide.
©2016 Datacolor Inc. Datacolor and other Datacolor product trademarks are the property of Datacolor Inc.
Windows is either a registered trademark of Microsoft Corporation in the United States and/or other countries.

1. Connect USB Cable



Connect to Computer

2. Connect Power Cord



Connect to Outlet

3. Turn power on. Locate black trap, white tile and green tile in accessories drawer.

4. Launch a Datacolor program, and calibrate* the instrument.



Power Switch



Calibration Accessories

Part No. 019-400020

* See User's Guide on USB drive for detailed instructions.